



Notification to Owners and Users

February 21, 2006

Luxfer Gas Cylinders requests your help in locating a small group of Luxfer composite cylinders that may not have been properly autofrettaged and/or hydrostatically tested by a third-party inspector, Arrowhead Industrial Services, Inc. Records indicate that some of these cylinders may have been sold to you.


Luxfer has verified that the cylinders are safe based on thorough testing, detailed engineering analysis and data collected from many cylinders already recovered from the affected group. Every cylinder thus far tested has passed all required tests without incident. However, remaining cylinders must be recovered and tested as quickly as possible.

To determine whether you have cylinders that need to be tested, please compare serial numbers of your Luxfer cylinders that have hydrostatic test dates from May through September 2005 with serial numbers listed on the Luxfer website at www.luxfercylinders.com/ctest. (The sample label below shows where to find the serial number and hydrostatic test date.)

Once you have determined which cylinders, if any, need to be tested, please call this toll-free number: **1-800-355-3156**. A Luxfer customer-service representative will arrange to have your cylinders tested and returned to you at no charge.

We apologize for any inconvenience this may cause you. Please be assured that Luxfer will make every effort to get your cylinders back to you as quickly as possible.

Thank you for your understanding and assistance.

	TC-SU 5134-310	
	DOT-E 10915-4500	
Serial Number	OK 7507	LUXFER
Hydro Date month / year	12  98	REE: 78
	Luxfer Part Number L45M	
	WARNING!! Do not fill if damage has caused strand unraveling.	
	MADE IN USA	